

Critical Defects Report



	Tire Protection System/Equipment					
Customer Name:		Site Name: Building XYZ				
Inspection ID:	5274	Site Address: 123 Sample St, Sampleton				
Inspector Name:	: Craig Rogers	Signature:	Mu	Date:	19/10/2007	
QBCC Licence N	No. 1184361					
Site Representative:		Signature:	Mac	Date:	19/10/2007	
as per (QDC 6.1 Quee defect that is likely to occupants of part or al	st and inspection of your fire rated access ensland) Or AS 1851 (2012). The definition render the fire safety installation inoperabil of the building if a fire or hazardous masket able to perform its normal function". F	n of a critical defect proble and the defect is reasterials emergency happ	ovided in the Building sonably likely to have sens". For the purpose	g Fire Safety F e a significant es of these note	Regulation 2008 is impact on the safe ss: inoperable is de	
as to prevent it from p and fire rated access p strongly recommend a	& Rescue Service would usually determin berforming to its normal function. For this branels may also affect a fire safety installa all defects be carried out as soon as possib 1851 (2012), outstanding defects will be n	reason, we believe son tion sufficiently so as t le within 30 days of rea	ne non-critical defects o prevent it from perfeceipt of reports. Note:	s if not all in fi orming its nor	re doors, smoke domal function and	
Door Number	Nature of Defect(s)	<u> </u>	7)			
FD2	Repair Closer to allow door to latch on closure. Repair Door b. ding on frame. Replace External Handle damaged components.					
FD3	Remove Security Latch hardware is non-compliant. Re, 'ace Door Non compliant to AS 1851. No tags fitted to door.					
FD6	Replace Door Non compliant to AS 18:	51. N gs fit. 1 to c	ot.			
FD12	Repair Closer to stop door from slamming colosure. Repair Door service required. Replace Lock lock not latching on closure. Require Lorient Seals due to excess e gap to hinge stile.					
FD13	Replace Door Non compliant to AS 18	1. vo tags fitted to do	or. Require Striker pla	ate damaged co	omponents.	
FD14	Repair Head Latch fitted to wrong s. e	of door.				
Program Trimos		W	ritten Quete Require	ad.	VES NO	
· · · · · ·		W	ritten Quote Require	ed:	YES NO	
Material Required:		W	ritten Quote Require	ed:	YES NO	
hat this building is in To authorise Touchwood	CE: We attach for your attention the renspected and tested at intervals in compod Doors to rectify the defects described a	equired remedial worl	ks to non-compliance rt MP6.1 and A.S 18	e doors and p 51 (2012)		
Material Required: Access Required: MPORTANT NOTI hat this building is in to authorise Touchwood nquiries@touchwood	nspected and tested at intervals in comp od Doors to rectify the defects described a ldoors.com.au	equired remedial worldiance with QDC, parabove, please complete	ks to non-compliance rt MP6.1 and A.S 18: the following details	e doors and p e 51 (2012) and email to	anels as nominato	
Material Required: Access Required: MPORTANT NOTI hat this building is in to authorise Touchwood nquiries@touchwood Order No:	nspected and tested at intervals in comp od Doors to rectify the defects described a doors.com.au	equired remedial world bliance with QDC, parabove, please complete	ks to non-compliance rt MP6.1 and A.S 18	e doors and p e 51 (2012) and email to	anels as nominato	
Material Required: Access Required: MPORTANT NOTI hat this building is in to authorise Touchwood nquiries@touchwood Order No:	nspected and tested at intervals in comp od Doors to rectify the defects described a ldoors.com.au	equired remedial world bliance with QDC, parabove, please complete	ks to non-compliance rt MP6.1 and A.S 18: the following details	e doors and p e 51 (2012) and email to	anels as nominato	

1/1

Touchwood Doors - QBCC Licence No. 82028