

YEARLY CONDITION REPORT

Report Number: 305410-07

Period Covered: 20/10/2006 to 19/10/2007


Responsible Entity:

Responsible Entity's Address:

Premises: Building XYZ
123 Sample St, Sampleton

System Type: Fire Door, Non-rated Door, Access Panel, Smoke Door

Design Standard Applicable: Passive Fire and Smoke Containment Systems

Statement:	I confirm that the system referred above has been inspected and tested where applicable to QDC 6.1, part MP6.1 and AS1851 2012 as per attached schedule of inspections from 20/10/2006 to 19/10/2007.		
System Defects:	Please refer to attached System Defects Report.		
Attachments:	Inspection Reports, Logbooks, Defects Reports, Rectification Reports, Certificates, Schedule of Inspections		
Service Provider Representative:			
Name:	John Smith		
Signature:		Date:	5/05/2022
Service Provider:			
Name:	Touchwood Doors	QBCC Licence No.	82028
Address:	35 Proprietary St, Tingalpa QLD 4173		