

ANNUAL SYSTEM CONDITION REPORT

Report Number: 305410-07

Period Covered: 20/10/2006 to 19/10/2007


Building Principal:

Principal's Address:

Premises: Building XYZ
123 Sample St, Sampleton

System Type: Fire Door, Non-rated Door, Access Panel, Smoke Door

Design Standard Applicable: Passive Fire and Smoke Containment Systems

Statement:	I confirm that the system referred above has been inspected and tested where applicable to QDC 6.1 and AS1851 2012 as per attached schedule of inspections from 20/10/2006 to 19/10/2007. For further details please visit www.fire.qld.gov.au press tab under Building Fire Safety and Building Fire Safety Regulations 2008 page 38 to 43 or call QLD fire and rescue community services 36351500.		
System Defects:	Please refer to attached System Defects Report.		
Attachments:	Certificates, Schedule of Inspections		
Contractor's Representative:			
Name:	James Riordan		
Signature:		Date:	26/05/2015
Contractor:			
Name:	Touchwood Fire Doors	QBCC Licence No.	82028
Address:	35 Proprietary St, Tingalpa QLD 4173		

IMPORTANT NOTICE: We attach for your attention as outlined above as nominated that this building is inspected and tested at intervals in compliance with QDC, part MP6.1 and A.S 1851 (2012)